

Inspection Report

Vehicle

Registration Plate

Inspection Number

2023 Kia Sportage NQ5 GT-Line MY23 5dr

CI R445

672D75

5st 8sp 2.0L

VIN

Date Created

08/11/2024

Odometer

17,620

VEHICLE INFORMATION

Year Make

023 k

Model VIN

Sportage NQ5 GT- KNAPX81CSP7190410

Line MY23 5dr 5st

8sp 2.0L

Build Date

Compliance Date

06/202 06/202

TYRE SUMMARY

Front Left Front Right

ass Pas

Rear left Rear Right

Pass Pass

Spare Wheel Diameter

Pass 18 Inch (Front) | 18

Inch (Rear)

VEHICLE SPECIFICS

Keys Servicebook

1 Key Present

Service History Last Service Date

Present 03/07/2024

Last Service Mileage Road test

1.976 KMS Yes

General Comments Driv

Second key with partner. No fluid leaks at time of

inspection. All engine oils fine at time of inspection.

Customer: No previous or current hail damage.

Vehicle has had windscreen replaced in the past

Inspector: No evidence of hail damage at time of

inspection

Road Test Comments

Drove as expected at time of inspection

Drive Train

Body Type MUV/SUV

Fuel Type

Disease

Transmission Color

Damage Location Internal Boot Area	Damage Description Has minor scuffing	Estimated Cost To Repair Will need repair if	
		buyer	
		chooses	a 11.
Damage Location	Damage Description	Estimated	
Other	Drivers door entrance has scuffing	Cost To Repair	
		Will need	
		repair if	
		buyer	1
		chooses	
Damage Location Other	Damage Description LHR wheel has minor scratches	Estimated Cost To Repair	
		vviii i leed	TO CO

Inspection Report







































VIN: KNAPX81CSP7190410

RAV Date of Entry	Entry Pathway Sub-Category	Approval Number	Approval Holder	vcc	Make	Model	Build Date	GVM / ATM (kg)	Tare (kg)	Power (kW)	Seats	Authorised by Name
20/06/2023	Type Approval - Standard	VTA- 060012	KIA MOTORS CORPORATION	MA	KIA	NQ5	05/2023	2260	1759	137	5	KIA MOTORS CORPORATION

Decisions: The Register of Approved Vehicles (RAV) provides information about road vehicles provided in Australia under the Road Vehicles Standards Act 2018 (RSA). The Department of Infrastructure, Transport, Regional Development, Communications and the Arts (the department maintains the RAV for piblics used does not accept any exhibition for the Infrastructure and another Control (Infrastructure).







Inspection Disclaimer

This is a non-mechanical, visual inspection only. The representative or company carrying out the inspection will not be responsible for any damage/defects before or after the inspection is carried out. This includes any items that may not be visually identifiable at the time of inspection. The inspection is only current for the date and time of inspection. It is not a roadworthy check nor can it be used as one. It is the buyers responsibility to assess the vehicles condition at time of sale. The inspection is to carry out a visual overview of the vehicles condition at the time of inspection. During this inspection, vehicle components will not be removed. Subject to any applicable laws, the representative or company will no provide any guarantee, warranty or representation regarding the reliability, accuracy, nature or completeness of any information contained in the inspection. The report will not hold any other guarantees, warranties, representation or fitness of information contained in the inspection for any other purpose. The representative or company will not be responsible for any terms of agreements or transactions or conversations between any persons in relation to any vehicle inspected. The representative or company will not be responsible for any disputes/contention between parties in relation to any transactions. The representative or company will not be liable to you for any loss of use, production, revenue, business or data. They will not cover any financial costs, increases in operating cost, economic loss (both indirect or consequential loss or damage).